

Sand Point Health Clinic 02.09-10.2006



South facade, horizontal siding, temporary water-proofing over air barrier.



South facade, horizontal siding and temporary waterproofing over air barrier.



Transition trim between horizontal and vertical siding, south facade.



Completed siding, eave soffit and fascia, windows and exterior louver at dental wing.

Sand Point Health Clinic
02.09-10.2006



Extent of horizontal siding on northwest facade.



East facade siding in progress at the ambulance bay.



Installed air handling unit in the Mechanical Room



Main duct-runs out of the Mechanical room and through associated wall framing.

Sand Point Health Clinic 02.09-10.2006



Vertical control joint in gypsum wallboard. Current extent of gypsum wallboard shown. Examples of installed sprinkler piping and electrical rough-in visible. South face of interior shear wall at Waste 145



Secondary front entrance; sound insulation, acoustic sealant, vapor retarder, metal wall framing, gypsum wallboard, aluminum storefront and sprinkler main visible.



Metal framed full height interior partition wall with acoustical insulation, fire-blocking and current extent of gypsum wallboard shown.



Looking east along main corridor, main ducting-runs, acoustical insulation and extent of gypsum wallboard visible.

Sand Point Health Clinic
02.09-10.2006



Mechanical ducting and interior of exhaust louvers along the clerestory wall above Lab 130.



Metal framed full height partition wall at Exam 120. View looking west from the Nurse's Station.



Exterior wall insulation, vapor retarder, gypsum wallboard, acoustical sealant and elastomeric membrane flashing.



Main corridor looking west from the Nurses Station. Gypsum wallboard installed floor to ceiling along sections of the interior shear walls.

Sand Point Health Clinic 02.09-10.2006



Mechanical ducting and equipment above the main entrance, looking towards the dental wing. Metal framed partition walls of the conference room and public restrooms beyond.



Northwest corner of the main conference room. Cement fiberboard trim pieces in foreground.



Interior of Dental wing showing extent of gypsum wallboard, insulation, mechanical ducting and exhaust louver.



Interior wall of the Dental wing showing extent of gypsum wallboard and metal framed partition walls. Example of excellent ductwork coordination and installation.